



Jul-21-00 2:42PM;














FIG. 3c





Fig. 3e





ISSYSON CELIC





Fig. 35

Fig. 3g






Fig. 3h

Sent By: Equipe Communications;






Fig.3i


Sent By: Equipe Communications;









Fig. 3j







COLLEO. COEZECE

Fig. 3L

L924 BATCH

Operant=BATCH Operator=Execute Version=V1_1_0_0 924a Task = execute-SPATH 9746 -Task2=execute-PVC 924c-Task3=execute-SPVC 924d - Task4=load-SPVC-spvc1 924 — Task5=execute-SPVC 924 — Task6=load-SPVC-spvc2 924c—Task7=execute-SPVC

9249 — Task50=sct-SPATH-PortID-3
9240 — Task51=execute-SPATH
9241 — Task52=sct-SPATH-SlotID-2 924) Task53=execute-SPATH

DOEZZECH COLLOC

Fig.34

K925

Operant=BATCH Operator=Execute

Version=V1_1_0_0

925 Task1=execute-CONTROL

9255 -Task2=execute-SPATH

925c -Task3=set-SPATH-PortID-3

925d Task4=execute-SPATH

Task61=set-CONTROL-System-192.168.9.201 GASS — Task62=execute-CONTROL

9259 —Task63=execute-SPATH

925h-Task108=close

HOME 7 HOU . CHAIDO

925; -Task109=set-CONTROL-Server-Server1

G257 Task111=execute-CONTROL
G257 Task111=execute-CONTROL

Task112=execute-SPATH

Sent By: Equipe Communications






Fig.4a




Fig. 4b

Sent By: Equipe Communications








Fig. 4c










	::::::::::::::::::::::::::::::::::::::		
		No.	
General Policies (Serv	TES TOTAL COST		
		72.5	
User Cannot Change P	assword:		
	Michigan Street Control of the Contr		
Account Disabled			
	illian syrate		
☑ User Can Add Devices			
	User Session Timeou	t: 15 Minutes	
		i Salasin Emperimento de partiro de la comunida. Transportante de la comunidad	
and the second of the second	ок .	Cancel	

Fig. 49

Sent By: Equipe Communications

Fig. 4h



maral fore	el Sever	Devices		9 243		
Device	READ	READWRIT	E Retry:	Timeou		Add
92.168.9.202	public	equipe	3	5	162	
92.168.9.205	public	equipe	3	5	162	Delete
92.168.9.216	public	equipe	3	5	5012	31000

Fig. 4i

K909





Fig. 4j



CARD TABLE


47	:		• • •		•••	• • •
H C	NO.	1 2	• • •	5	• • •	12
() () ()	VERSION SLO	ω 4	• • •	-	• • •	-
	CWD TYPE	0XF002 0XF002	•••	0X6002	•••	0XF002
	<u>O</u> d	500	•••	505	• • •	513
		16 a)	16e		16 n


FIG. 6

PORT TABLE

4 .						••	•		• • •	
SLOT NO.	-		-	-		• •	•	8	•••	
VERSION SLOT	-	-	-			٠	• •	-	• • •	
PORT TYPE	00620	00620	00620	00620	00820	٠	• •	00620	•••	
<u>Q</u>	1500	1501	1502	1503	1504	-	••	1600	•••	
		445	440	449	46.9	3)		-		

FIG. 7








FIG. 10

Service Endpoint Table 76

	Service	Port PID
	Endpoint #	POHPIO
78 —	1	1500
80	2	1501
82 —	3	1501
84	4	1501
86	5	1502
88 —	6	1502
90	7	1503 -
92	8	1503
94	9	1503
168	10	1502
		:

FIG. 11a

Logical to Physical Card Table 100

	98	102	104	/
		/ .	/ /	1
		Primary	Back-up	
	LID	PID	PID	
106-	. 30	500	513	
109	31	501	513	
:		į	:	

FIG. 11b

Logical to Physical Port Table 10,1

	98	102	104	,
	/		/	\checkmark
		Primary	Back-up	Ì
	LID	PID	PID	ĺ
107—	40	1500	1600	
		:	i	

ATM Group Table 108

Group #	Card LID	•••
1	30	
2	30	
3	30	
4	30	

FIG. 13


ATM Interface Table 114

	ATM	ATM	CC	
	<u>I</u> F	Group	SE	•••
	1	1	1	
	2	1	1	
	3	1	1	
	4	2	2	
	5	2	3	
	6	2	4	
	:	:	:	:
170	12	3	10	
İ	:	:	:	i

FIG. 14

Software Load Record 128a

_		✓	
130	Control Shim	LID	 1 32
134——	alm-cntl.exe	30	}







FIG. 16a









FIG. 16d












FIG. 19











FIG. 22

FIG. 23













FIG. 27





	Group Table 108'								
			447		449				
	_	·							
	1	Group	Primary	Backup					
	- 1	#	Card LID	Card	• • •				
		л	Odro Ero	LID					
450		11	30	31					
451		2	30	31					
452		3	30	31					
453		4	30	31					
454		5_	31	32					
455		6	31	32	,				
456		7	31	32					
457		8	31	32					
458		9	32	30					
459		10	32	30					
460		11	32	30					
461		12	32	30					
		:	:	•	•				
		·	•		•				








Fig. 31c




Fig. 32a 472-475 464-467 480-483 PR PR MIA £1TA 486.487 BC ВC ATM 470-471 478 479 вс ВС BC MTA MTA ATM

Fig. 32b







Fig. 32c










Fig. 34a






FIG. 34b

Sent By: Equipe Communications; 781 795 2031; Jun-7-00

Jun-7-00 4:55PM; Page 2/2








FIG. 38

Path Table 600
Sath UP Time Slot Time
LID LID Slots

•		• • •
# of Time Slots	က	• • •
Time Slot	4	• • •
حل 20م 100	1231	• • •
Path	1666	• • •
	602	

FIG. 39

Service End Point Table 76'

	•		•••
610	Path PID	1666	•••
	FC Time Slot		• • •
909	FC Slice		•••
	FC LID		•••
	O #	-	• • •
	S #	878	• • •
		604 —	

~;







Fig. 40

FIG. 4

FIG. 41a








181 795 2031;

101-6-00 4:26PM;







FIG. 46

665

LTS







FIG. 48

Jul-6-00 4:27PM; pag

181 795 2031;


181 795 2031;



Page 11/15

Jul-6-00 4:27PM;


181 795 2031;




1802 367 187

Fig. 52

804




Extractor FIG. 53



Page 14/15

Jul-6-00 4:28PM;


1802 262 187




Page 15/15

Jul-6-00 4:28PM;

181 795 2031;





845 Enable Receiver Port Yes 22 Test Path Table 841 Ingress Egress Ingress Monitor 844 # of # of Slots 3 3 3 Time Slot UP Port LID 1232 1233 1233 Path LID 1666 1666 1666 842 -843 -844 -

FIG. 58